

Cable Services Product Bulletin Number: 005

Global Marine Systems Limited;
A member of the UJ/UC Consortium

22nd February 2000



www.ujuc.com

New Pirelli Hydrogen Seal Solution.

Resulting from a continuing review of product design, Global Marine has improved the design for Pirelli 14mm and Pirelli 18.5mm hydrogen managed Universal Joints. Improvements to the method of fixing the copper seal to the ferrule and to the copper tube of the cable have been made. The requirement for soldering the seal has been replaced by a more user-friendly Loctite 638 adhesive solution.

Effective from the kit serial numbers shown in the attached table, the solder and terylene tape are removed from all end specific kits and only Loctite 638 should be used. It is recommended that Loctite 638 be used, in replacement for solder on earlier kits. No change to piece parts is required.

Loctite 638 can be procured by customers from their local Loctite supplier, or alternatively directly from Global Marine as KIT15060 (Loctite 638) will provide sufficient adhesive for approximately 20 joints.

KIT15060

CSPB005-01

Pirelli 18.5mm Variants:	KIT No.	Effective Serial Number
LW	KIT20000	0076
LWP	KIT20010	0143
LWA	KIT20020	0076
SA	KIT20030	0111
HDA	KIT20040	0049
RA	KIT20050	0013
HRA/E	KIT20060	0019
Pirelli 14mm Variants:		
SA	KIT21030	0017
DA	KIT21040	0017