Universal Jointing Consortium Bulletin Number: UJCB078 Issue 2

12 November 2018


www.ujconsortium.com



C-SAMs Extruder Band Heater Replacement

The C-SAMs Extruder is heated by Band Heaters (Part # P15SS0167) configured in two zones, Loop 5 and Loop 6. In the figure below these are marked in different colors.

If for any reason one or more of the band heaters in either group require replacement, then the complete set of three heaters in that Zone will need to be replaced. If not, the extruder heating may not perform in the way in which the system was designed or qualified.



Replacement heaters are found in the Spares Kit 15C or A24Ce, as applicable. For replacement Band Heaters please contact any UJC member using the contact details below.

Note: This UJC Bulletin 078 Issue 2 corrects a part number error shown in Issue 1.

If you have any queries concerning these changes, please contact the UJ Consortium Co-ordinator.

Contacts for the UJC	General Matters	Technical Matters
UJC Coordinator	Mr Jon Reynolds E-mail: coordinator@ujconsortium.com	Mr Jon Reynolds E-mail: coordinator@ujconsortium.com
Alcatel Submarine Networks	Mr Pierre Gaillard E-mail: pierre.gaillard@asn.com	Mr Romuald Lemaitre E-mail: romuald.lemaitre@asn.com
Global Marine	Mr Craig Beech E-mail: craig.beech@globalmarine.co.uk	Mr Craig Beech E-mail: craig.beech@globalmarine.co.uk
Kokusai Cable Ship Co., Ltd.	Mr Hiroyuki Kuroda E-mail:kuroda@k-kcs.co.jp	Mr Shuichiro Takeda E-mail: takeda@k-kcs.co.jp
	Ms Eriko Yamate E-mail: yamate@k-kcs.co.jp	Mr Tatsuya Shimobachi E-mail: shimobac@k-kcs.co.jp
SubCom	Mr James Jackson E-mail: jfjackson@subcom.com	Mr Joe Man E-mail: jman@subcom.com

This bulletin is the copyright of one or more members of the UJ Consortium (Alcatel Submarine Networks, Global Marine, Kokusai Cable Ship Co. Ltd. and SubCom). No information contained in this bulletin may be reproduced in any form or by any means without express permission from the relevant copyright holder.